640/1260 – Soft/Hard Reset

Question:

How do I reset my ZonePRO 640/1260?

Answer:

Hard Reset (resets everything)

1. Power down the unit by pulling the IEC cable.
2. Simultaneously hold the <2> button (next to the display) while powering on the unit until the following message appears: !: HARD RESET?
3. Press the <UTIL> button (large knob) in to reset the unit.
   OR
4. Pressing the <PAGE 1> button will abort the System Reset sequence and the unit will reboot normally.

Soft Reset (resets everything except user programs)

1. Power down the unit by pulling the IEC cable.
2. Simultaneously hold the <3> button (next to the display) while powering on the unit until the following message appears: !: SOFT RESET?
3. Press the <UTIL> button (large knob) in to reset the unit.
   OR
4. Pressing the <PAGE 1> button will abort the System Reset sequence and the unit will reboot normally.