

Question:

Why am I getting an MMER code on my MAC Quantum?

Answer:

The “MMER” or missing module error is caused by a lack of communication with one or more modules that should be present in your fixture. It can be caused if a module is missing or not correctly connected or after the unit has been serviced. Please contact Martin Tech support for assistance with this error.

About HARMAN Professional Solutions

HARMAN Professional Solutions is the world's largest professional audio, video, lighting, and control products and systems company. Our brands comprise AKG Acoustics®, AMX®, BSS Audio®, Crown International®, dbx Professional®, DigiTech®, JBL Professional®, Lexicon Pro®, Martin®, and Soundcraft®. These best-in-class products are designed, manufactured and delivered to a variety of customers in markets including tour, cinema and retail as well as corporate, government, education, large venue and hospitality. For scalable, high-impact communication and entertainment systems, HARMAN Professional Solutions is your single point of contact. www.harman.com