

v1.0

No Output from Fog / Haze Machine

28-Jan-22

Question:

Why did my unit stop outputting fog/haze?

Answer:

Your unit may have stopped outputting fluid for a number of reasons.

- First check to ensure your fluid reservoir has fluid.
- If you have fluid in the reservoir and no fog is produced it may be necessary to prime the machine.

If you still have no output please consult a Martin technician for additional support.

About HARMAN Professional Solutions

HARMAN Professional Solutions is the world's largest professional audio, video, lighting, and control products and systems company. Our brands comprise AKG Acoustics®, AMX®, BSS Audio®, Crown International®, dbx Professional®, DigiTech®, JBL Professional®, Lexicon Pro®, Martin®, and Soundcraft®. These best-in-class products are designed, manufactured and delivered to a variety of customers in markets including tour, cinema and retail as well as corporate, government, education, large venue and hospitality. For scalable, high-impact communication and entertainment systems, HARMAN Professional Solutions is your single point of contact. www.harman.com