

v1.0

SmartMAC – RCER Error

5-Jul-22

Question:

What is RCER error on SmartMAC?

Answer:

RCER is Real Time Clock Error, and it indicates that the coin battery on the mainboard needs replacement. It is type CR1225 that are used and is mounted in a battery holder.

About HARMAN Professional Solutions

HARMAN Professional Solutions is the world's largest professional audio, video, lighting, and control products and systems company. Our brands comprise AKG Acoustics®, AMX®, BSS Audio®, Crown International®, dbx Professional®, DigiTech®, JBL Professional®, Lexicon Pro®, Martin®, and Soundcraft®. These best-in-class products are designed, manufactured and delivered to a variety of customers in markets including tour, cinema and retail as well as corporate, government, education, large venue and hospitality. For scalable, high-impact communication and entertainment systems, HARMAN Professional Solutions is your single point of contact. www.harman.com