

v1.0

RUSH MH2 - No Output

30-Jun-22

Question:

No output on my RUSH MH2, the led driver PCBA has been replaced and still not working.

Answer:

Check the 485 cable between the mainboard and led driver PCBA, if that is intact, replace the mainboard.

About HARMAN Professional Solutions

HARMAN Professional Solutions is the world's largest professional audio, video, lighting, and control products and systems company. Our brands comprise AKG Acoustics®, AMX®, BSS Audio®, Crown International®, dbx Professional®, DigiTech®, JBL Professional®, Lexicon Pro®, Martin®, and Soundcraft®. These best-in-class products are designed, manufactured and delivered to a variety of customers in markets including tour, cinema and retail as well as corporate, government, education, large venue and hospitality. For scalable, high-impact communication and entertainment systems, HARMAN Professional Solutions is your single point of contact. www.harman.com